



FOR POSSIBLE PRESENTATION TO THE UNITED STATES COAST GUARD

Office: **Houston**

Date: **04 February 2013**

This certificate is issued to the Master of "Carnival Triumph" at the request of the owner's representative for possible presentation to the United States Coast Guard to certify that the undersigned Surveyor to Lloyd's Register North America did attend on board the:

SHIP'S NAME: CARNIVAL TRIUMPH
LR/IMO No.: 9138850
CALL SIGN: C6FN5
GROSS TONS: 101,509
PORT OF REGISTRY: NASSAU

On February 2nd, 2013 while the vessel was at Galveston Cruise Terminal, in order to examine damage to the ship's generators.

Nature of Deficiency:

<u>Code</u>	<u>Description</u>	<u>Cite (convention)</u>	<u>Action Req'd²</u>
1430	The vessel reported a short in the high voltage connection box of one of the ship's generators causing damage to the electrical cables within the connection box. The condition of the ship and its equipment shall be maintained to conform to the provisions of the present regulations to ensure that the ship in all respects will remain fit to proceed to sea without any danger to the ship or persons onboard.	SOLAS 2009 Chapter 1, Regulation 11	50ac

Note- Code 50ac is to rectify deficiencies with 30 days to the satisfaction of RO/RSO and Coast Guard.

The vessel was not the subject of a PSC detention.

Now Done:

1. The generator circuit breakers have been examined and tested by the maker's representative and found to operate satisfactory.
2. The high voltage electrical connection box on No. 6 alternator has been repaired. The alternator has been tested satisfactorily by Lloyd's Register and the maker's representative and has now been placed back in service.
3. No. 5 Alternator remains out of service pending repairs of the stator. A Condition of Class has been imposed with a due date of April 2013.

In view of the survey now completed reports are being forwarded to the Committee of Lloyd's Register recommending that the ship's class be maintained.

(Handwritten signature)
 Lloyd's Register North America, Inc.
 John Eck
 Houston-Port Office
 Surveyor to Lloyd's Register North America, Inc.
 A subsidiary of Lloyd's Register Group Limited

Lloyd's Register, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as the 'Lloyd's Register Group'. The Lloyd's Register Group assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register Group entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.